

Kinder Morgan – Argo, IL

8500 West 68th Argo, IL 60501

Loading Hours: Office Hours:

Mon – Fri 5:00 h – 17:00 h Mon – Fri 5:00 h – 17:00 h

Scheduling Requirements

- Carrier must call KM dispatch 24 hrs. in advance to schedule an appointment time for loading. Phone number: 708 496 2865.
- Carrier must complete KM Request to Load form prior to arrival at the terminal. (See attachment)



Scale House 1 & 2.p

- Driver must have washout slip dated within 72 hours of loading and also calibration • chart for trailer that is loading.
- KM is a TWIC compliant terminal. Driver will need TWIC card in his/her possession to • be verified by dispatch prior to loading.

Truck Loading Requirements

ALL DRIVERS MUST HAVE PROPER PPE:

- Hard hat
- Goggles
- HI Visibility Reflective Fire Retardant long pants & long sleeved shirts
- Chemical resistant gloves
- Safety toe boots

YOUR OUTER MOST LAYER OF CLOTHING MUST BE REFLECTIVE & FIRE RETARDANT

PRODUCTS WITH HAZARDOUS VAPORS

- 2-Ethylhexanoic Acid
- Acetic Acid •
- Formic Acid

Require Full face respirator (on hand)

COOROSIVE PRODUCTS

- 2-Ethylhexanoic Acid
- Acetic Anhydride .
- Formic Acid

Require Fire retardant chemical suit*

HEATED PRODUCTS

- 6 Oil •
- NPG90

Require Face Shield

- Acetic Anhydride
- DMAPA
- MEA
- Acetic Acid
- DMAPA
- MEA
- DEA
- P2000 & TEA