

OQ
Site addresses and information for Customer Pickup (CPU)



Kinder Morgan – Argo, IL

8500 West 68th
Argo, IL 60501

Loading Hours: Mon – Fri **6:00 h – 15:00 h**
Office Hours: Mon – Fri **7:00 h – 16:00 h**

Scheduling Requirements

- Carrier must call KM dispatch 24 hrs. in advance to schedule an appointment time for loading. Phone number: 708 496 2865.
- Carrier must complete KM Request to Load form prior to arrival at the terminal. (See attachment)



9005 - Argo, IL - RFL
Scale House 1 & 2.p

- Driver must have washout slip dated within 72 hours of loading and also calibration chart for trailer that is loading.
- KM is a TWIC compliant terminal. Driver will need TWIC card in his/her possession to be verified by dispatch prior to loading.

Truck Loading Requirements

ALL DRIVERS MUST HAVE PROPER PPE:

- Hard hat
- Goggles
- HI Visibility Reflective Fire Retardant long pants & long sleeved shirts
- Chemical resistant gloves
- Safety toe boots

YOUR OUTER MOST LAYER OF CLOTHING MUST BE REFLECTIVE & FIRE RETARDANT

PRODUCTS WITH HAZARDOUS VAPORS

- 2-Ethylhexanoic Acid
- Acetic Acid
- Formic Acid
- Acetic Anhydride
- DMAPA
- MEA

Require Full face respirator (on hand)

COOROSIVE PRODUCTS

- 2-Ethylhexanoic Acid
- Acetic Anhydride
- Formic Acid
- Acetic Acid
- DMAPA
- MEA

Require Fire retardant chemical suit*

HEATED PRODUCTS

- 6 Oil
- NPG90
- DEA
- P2000 & TEA

Require Face Shield